

# Site Accessibility Evaluation



**Industrial Park**  
**108 Industrial St**  
**Denton, TX 76201**

**Accessibility Evaluation**

***Inspection Date: 04/16/2021***

***Inspector: N/A***

**Prepared By**



**(972) 434 - 0068**

**[www.accessology.com](http://www.accessology.com)**

***Table of Contents***

---

<b>Barriers</b> .....	<b>3</b>
<b>Path of Travel</b> .....	<b>3</b>
<b>Path of Travel</b> .....	<b>3</b>
<b>Cost Summary</b> .....	<b>8</b>

## Path of Travel : Path of Travel

### Barrier: 1

There is no accessible route to the dog waste bag dispenser.

#### Citation:

2010 ADAS Section: 206.2.2

1991 ADAAG Section:  
4.1.2(1)

#### Current Condition:

There is no accessible route  
to the dog waste bag  
dispenser.

#### Budget Cost:


Base Cost: \$750.00  
Contingency Cost: \$150.00  
Design Cost: \$112.50  
Total Cost: \$1,012.50

### Possible Solutions:

Provide an accessible route of travel and the required clear floor space to the dog waste bag dispenser.

### Barrier Priority:

Level 5 (Medium): Access to goods and services issues (DOJ Level 2) – severely out of compliance



## Path of Travel : Path of Travel

### Barrier: 2

There is no accessible route to the table.

#### Citation:

2010 ADAS Section: 206.2.2

1991 ADAAG Section:  
4.1.2(1)

#### Current Condition:

There is no accessible route to the table.

#### Budget Cost:


Base Cost: \$1,500.00  
Contingency Cost: \$300.00  
Design Cost: \$225.00  
Total Cost: \$2,025.00

### Possible Solutions:

Provide an accessible route of travel to the table.

### Barrier Priority:

Level 6 (Medium): Parking or exterior accessible routes (DOJ Level 1) – minimally out of compliance  
Access to goods and services (DOJ Level 2) – moderately out of compliance  
Restrooms (DOJ Level 3) – severely out of compliance



**Path of Travel : Path of Travel**

**Barrier: 3**

There are no accessible tables.

**Citation:**

2010 ADAS Section: 226.1

1991 ADAAG Section: 5.1

**Current Condition:**

There are no accessible tables.

**Budget Cost:**

Base Cost: \$750.00  
Contingency Cost: \$150.00  
Design Cost: \$112.50  
Total Cost: \$1,012.50

**Possible Solutions:**

Provide an accessible table at the park.

**Barrier Priority:**

Level 5 (Medium): Access to goods and services issues (DOJ Level 2) – severely out of compliance



**Barrier #3 Additional Barrier Photos**



## Path of Travel : Path of Travel

### Barrier: 4

There is no accessible route to the table.

#### Citation:

2010 ADAS Section: 206.2.2

1991 ADAAG Section:  
4.1.2(1)

#### Current Condition:

There is no accessible route to the table.

#### Budget Cost:


Base Cost: \$1,500.00  
Contingency Cost: \$300.00  
Design Cost: \$225.00  
Total Cost: \$2,025.00

### Possible Solutions:

Provide an accessible route to the table.

### Barrier Priority:

Level 6 (Medium): Parking or exterior accessible routes (DOJ Level 1) – minimally out of compliance  
Access to goods and services (DOJ Level 2) – moderately out of compliance  
Restrooms (DOJ Level 3) – severely out of compliance



## Cost Summary

<b>Item</b>	<b># of Barriers</b>	<b>Total Item Cost</b>
High Priority	0	\$0.00
Level 1	0	\$0.00
Level 2	0	\$0.00
Level 3	0	\$0.00
Level 4	0	\$0.00
Medium Priority	4	\$6,075.00
Level 5	2	\$2,025.00
Level 6	2	\$4,050.00
Level 7	0	\$0.00
Level 8	0	\$0.00
Low Priority	0	\$0.00
Level 9	0	\$0.00
Level 10	0	\$0.00
Level 11	0	\$0.00
Level 12	0	\$0.00
<b>Priority Total</b>	<b>4</b>	<b>\$6,075.00</b>